

## Aircraft Occurrences in July 2010

*Statistics reflect accident information entered into the computer by the research office and are current as of the date of this document.*

*The data herein is dynamic and is therefore subject to change due to updated information.*

Accident Ref	Date of Occ	Aircraft Type	Registration	Province	Area of Occurrence	Fatalities	Summary	Type of Operation
8800	06-Jul-10	Windlass Aquilla trike	ZU-CGD	TBA	Jag Airfield	0	right main wheel separated from aircraft, a/c dug into the ground, ground looped	Training
8801	09-Jul-10	ROBINSON - R44	ZS-OWT	NP	Wilgeriver	0	Engine failure, autorotation, followed by hard landing. Main rotor severed the tail boom	Private
8802	15-Jul-10	SG AVIATION - Rally	ZU-EWP	KZN	Light Flight Aerodrome	0	gust of wind on landing. Pilot lost directional control. a/c veered off runway and collided with windsock pole	Private
8803	14-Jul-10	ALOUETTE III	ZS-RKJ	EC	Next to Coe River (EL)	0	severe vibration in flight, pilot elected to do a auto rotational landing. Helicopter rolled on its side during landing	Training
8804	16-Jul-10	Jabiru J160	ZU-DWZ	Limp	Hento Private Strip	0	wire strike on approach for landing	Private
8805	16-Jul-10	DE HAVILLAND - DHC8-300	ZS-NLY	NC	Runway 20 Kimberly Aerod	0	landing on Runway 20 at Kimberley, the aircraft collided with a wild animal	Domestic Scheduled
8806	17-Jul-10	Windlass Aquilla	ZU-DXW	GP	Next to Bronkorstspruit Dam	0	Engine failure, pilot deployed the ballistic parachute. a/c sustained damages on wings and undercarriage	Private
8807	22-Jul-10	CESSNA - 182	ZS-RGN	MP	Hoedspruit	2	aircraft collided with mountains	Private
8808	22-Jul-10	ROBINSON - R22	ZS-RXV	GP	Rand Aerodrome	0	change in wind direction, a/c lost control, skids impacted the ground, a/c rolled to its right side	Training
8809	23-Jul-10	Y021MT03	ZU-TMA	TBA	Crystal Springs	0	The pilot encountered a powerloss during the landing at Crystal Springs. Just before coming to a final stop the aircraft	Private
8810	24-Jul-10	Aeroprakt	ZU-ESB	KZN	Pietermaritzburg	2	Pilot collided with a pole on take-off	Private
8811	01-Jul-10	Beech 58 - Baron	ZS-RCL	WC	Cape Town International	0	The pilot landed the aircraft without selecting the landing gear down	Private
8812	22-Jul-10	Bushbaby 450	ZU-ASL	FS	Bloemfontein	0	severe vibration in flight followed by emergency landing on a mound of soil. a/c nosed over	Private
8813	27-Jul-10	PIPER - PA-32	ZS-EWX	Limp	Louis Trichardt	0	Engine failure on take-off followed by forced landing. a/c entered a ditch and severed main landing gear	Commercial
8814	28-Jul-10	PIPER - PA-28	ZS-MJS	KZN	Virginia	0	Engine failure in flight followed by forced landing. Both wings were damaged	Private
8415	29-Jul-10	Robinson R 22	ZS-RRM	GP	Panorama Airfield	0	Pilot lost control when he was hoovering the aircraft. Aircraft crashed and sustained substantial damage	Private
8016	30-Jul-10	Eurocopter	ZS-RME	WC	FACT	0	Low rotor RPM, unable to recover, hard landing, main rotor severed the tail boom	Private

**Issued by Accidents and Incidents Investigations Division**

**Research Section**

**Enquiries, please contact**

**Ms Bongji Mtlorkwa**

**011 545 1238**

**083 451 2683**

[aiidinbox@caa.co.za](mailto:aiidinbox@caa.co.za)

*Last date of update: 01 December 2010*