

Aircraft Occurrences in February 2010

Statistics reflect accident information entered into the computer by the research office and are current as of the date of this document. The data herein is dynamic and is therefore subject to change due to updated information.

Accident Ref	Date of Occ	Aircraft Type	Reistration	Province	Area of Occurrence	Fatalities	Circumstances	Type of Operation
8745	1-Feb-10	Huges 269c	ZS-HWN	GP	Wonderboom	0	Tail boom made contact with the ground on take-off	
8746	3-Feb-10	Cessna 206	ZS-PNM	GP	Magaliesburg Ridge (PTA)	2	CFIT follwed by post fire impact	Private
8747	2-Feb-10	Windlass Aquilla	ZU-FDC	TBA	TBA	0	A/C collided with power lines during crop spraying operation	Crop Spraying
8748	5-Feb-10	Cessna 210	ZS-PFU	GP	FALA	0	Wheels up landing	
8749	6-Feb-10	Robinson R 44	ZS-PVE	O/B	Charles Prince Airport (Zimbabwe)	0	Loss of RPM after take-off	Training
8750	6-Feb-10	Windlass Trike	ZU-AWP	GP	Petronella	0	Pilot loss directional control on take-off	Private
8751	6-Feb-10	Raptor	ZU-DEX	MP	Alma Private Aero - Barberton	0	Low power on take-off, a/c stalled and crashed on garage roof	Private
8752	10-Feb-10	Cessna 172 M	ZS-PSW	GP	Vereeniging Aerodrome	0	Hard landing	Training
8753	11-Feb-10	Cessna 210	ZS-MJA	KZN	St. Lucia	0	Loss of engine oil pressure follwed by forced landing	Private
8754	11-Feb-10	Mooney M20J	ZS-DYK	GP	Brakpan Aerodrome	0	Nose gear collapsed on landing	Training
8755	12-Feb-10	Cessna F172M	ZS-PYL	GP	Tulisa Park	0	Loss of engine power followed by forced landing	Private
8756	14-Feb-10	Sling	ZU-TAF	KZN	Tinley Manor	0	Aircraft entered a flat spin and failed to recover, it crashed into the sea (aircraft could was not found after crashing into the sea)	Private
8757	16-Feb-10	Robinson R22	ZS-HAI	GP	Rand Aerodrome	0	Student lost control of aircraft during autorotation training	Training
8758	16-Feb-10	Cessna 177 RG	ZS-MRD	GP	Lanseria Aerodrome	0	Landing gear failed to extend, wheels up landing	Private
8759	17-Feb-10	RobinsonR 44	ZS-JRS	Limp	Thabazimbi	0	Aircraft collied with power lines on take-off from grass area next to the road	Private
8760	18-Feb-10	Comco Ikarus	ZU-DRW	TBA	Stanford Aerodrome	0	Loss of engine power on take off followed by forced landing, nosewheel assembly collapsed and propeller came into contact with the ground	
8761	20-Feb-10	Beech 55	ZS-PTC	FS	Hoopstad	1	Pilot lost control of the aircraft during take-off	
8762	22-Feb-10	Piper PA 18	ZS-DLI	KZN	Ballito	0	Aircraft impacted drainage ditch during landing	Private
8763	23-Feb-10	Rotary Air Force RAF 2000	ZU-DOR	WC	Saldanha	0	Speed decayed instantly and the gyrocopter landed hard	Private
8764	26-Feb-10	Rotary Air Force RAF 2000	ZU-EPM	NC	Aurgrabies	0	Engine power loss	Private

Issued by Accidents and Incidents Investigations Division

Research Section

Enquiries, please contact

Ms Bongzi Mtlakwa

011 545 1238

083 451 2683

aiidinbox@caa.co.za

Last date of update: 16 April 2010