

Aircraft Occurrences in October 2010

Statistics reflect accident information entered into the computer by the research office and are current as of the date of this document.

The data herein is dynamic and is therefore subject to change due to updated information.

Accident Ref	Date of Occ	Aircraft Type	Registration	Province	Area of Occurrence	Fatalities	Summary	Type of Operation
8842	01-Oct-10	Zealand LTD	ZU-CYX	MP	Schoemanskloof	0	Pilot encountered a downdraft which affected the altitude, loss of power, forced landing in mountainous area	Private
8843	02-Oct-10	Rainbow Aircraft (PTY) LTD	ZU-DHH	KZN	Ladysmith	0	Loss of power during take-off, a/c went on a ditch during forced landing	Training
8844	02-Oct-10	Windlass Trike	ZU-AZZ	GP	Aero 57 Airfield	0	a/c veered off the runway and collided with an embankment	Training
8845	08-Oct-10	Hughes 269C	ZS-HTJ	Limp	farm Eulalie, Marken district	0	Decay in main rotor rpm accompanied by increase in engine rpm, forced landing	Game Darting
8846	08-Oct-10	Tecnam	ZU-MIF		FAAP	0	Collision with fence during take-off, aircraft substantially damaged	Training
8847	09-Oct-10	BEECH - 35 BONANZA	ZS-KCC	GP	FAKR	0	Undercarriage collapsed during landing, propeller was damaged	Private
8848	11-Oct-10	Bellanca 7GCAA	ZS-MYH	GP	Klerksdorp	0	aircraft flipped over during taxi when the pilot applied brakes	Private
8849	12-Oct-10	Solo Wings CC	ZU-BWU	GP	Brits Airfield	0	Power loss in-flight, emergency landing followed	Private
8850	13-Oct-10	Sa Ravin Aircraft	ZU-XML	GP	FAKR	0	Pilot encountered a downdraft during landing, a/c landed on its wheels first, pilot lost directional control and veered off the runway. r/h wing and propeller damaged	Private
8851	11-Oct-10	Cessna 172	ZS-KNI	KZN	Harding	0	during landing, a/c failed to stop at the end of the runway, both wings struck two fence posts at the end of the runway	Private
8852	14-Oct-10	Comco Ikarus C 42	ZU-EUV	FS	FAKS	0	aircraft bounced on landing, loss directional control and yawed to the left of runway	Training
8854	14-Oct-10	Cessna 206T	ZS-PSD	0/B	Namibia	0	Hard Landing	Private
8855	18-Oct-10	Rotorway	ZU-DCI	WC	Near Morning Star Airfield	0	a/c impacted the ground during an autorotation and rolled over	Training
8858	23-Oct-10	Zenair C701	ZU-FHC	WC	Pieketburg Aero	0	Struck power lines during approach for landing and crashed	Private
8858	26-Oct-10	Cherokee Archer and Jabiru	ZS-KIN and ZU-BXA	GP	FAWB	0	ZS-KIN and ZU-BXA collided in midair at Wonderboom Aerodrome.	TBA
8859	29-Oct-10	PA 23-250	ZS-RPS	GP	FAGM	0	Student applied brakes after landing but the aircraft did not slow down. Engine was shut down, applied right rudder to turn away from fence. Left wing and nose struck the fence.	Training

Issued by Accidents and Incidents Investigations Division

Research Section

Enquiries, please contact

Ms Bongji Mtlokwa

011 545 1238

083 451 2683

aiidinbox@caa.co.za

Last date of update: 01 December 2010