

**SOUTH AFRICAN CIVIL AVIATION AUTHORITY
AIRCRAFT SAFETY DEPARTMENT**

**MAINTENANCE ADVISORY NOTICE
GENERAL # 046**

STOLEN AIRCRAFT COMPONENTS

Applicability: Owners, Operators and their associated Maintenance Organisations

Compliance

Compliance with this Maintenance Advisory Notice (MAN) is considered mandatory by this Authority.

1. Introduction

The SACAA has been notified of the following stolen aircraft components:

VENDOR	NOMENCLATURE	PART NUMBER	SERIAL NUMBER
Honeywell	IVA-81D VSI(TCAS Ind)	066-500001-1001	7235
Honeywell	IVA-81D VSI(TCAS Ind)	066-500001-1001	3931
Honeywell	IVA-81D VSI(TCAS Ind)	066-500001-1001	9866
Honeywell	IVA-81D VSI(TCAS Ind)	066-500001-1001	7770
Honeywell	IVA-81D VSI(TCAS Ind)	066-500001-1001	8093
Honeywell	IVA-81D VSI(TCAS Ind)	066-500001-1001	8229
Honeywell	IVA-81D VSI(TCAS Ind)	066-500001-1001	9557
Honeywell	IVA-81D VSI(TCAS Ind)	066-500001-1001	8344
Honeywell	CTA-81D TCAS Controller	071-01480-0017	1745
Honeywell	CTA-81D TCAS Controller	071-01480-0017	1510
Honeywell	CTA-81D TCAS Controller	071-01480-0017	1138
Honeywell	ANT-81A TCAS Antenna	071-500001-8102	5745
Honeywell	TPA-81A TCAS Processor	066-00000-2120	2574
Honeywell	TPA-81A TCAS Processor	066-00000-2120	4332
Honeywell	TPA-81A TCAS Processor	066-00000-2220	11967
Honeywell	TPA-81A TCAS Processor	066-00000-2220	8584
Honeywell	TPA-81A TCAS Processor	066-00000-2220	8792
Honeywell	TRA-67A Mode s Transponder	066-01127-1301	6408
Honeywell	TRA-67A Mode s Transponder	066-01127-1301	8263
Honeywell	TRA-67A Mode s Transponder	066-01127-1602	11405
Honeywell	TRA-67A Mode s Transponder	066-01127-1602	11428
Honeywell	TRA-67A Mode s Transponder	066-01127-1602	12606
Honeywell	DV-910 VSI	4067241-840	121476
Honeywell	DV-910 VSI	4067241-840	110492
Honeywell	EISDU	4056510-903	961034427
Honeywell	EISDU	4056510-903	98103859
Honeywell	EISDU	4056510-903	97043580
Honeywell	FMC	4052504-927	9905A261
Honeywell	WGB Windshear Computer	4059845-911	96041134
Gables	ATC Control Panel	G74901-4	773

Gables	ATC Control Panel	G74901-4	872
Teledyne	DFDAU	2222601-6	713
Rockwell-Collins	TTC-920A TCAS Controller	622-9288-005	225

These assemblies are regarded to be **Unapproved Parts** and may not be installed on aircraft.

2. Action Required

With immediate effect, all Maintenance Organisations shall inspect all their stock for the components listed in the table. Any component found shall be quarantined, and the SACAA notified immediately by sending an email to sdr@caa.co.za

3. Queries

Any queries as a result of this MAN should be addressed to the Manager: Defect Reporting at the following email address: sdr@caa.co.za or telephone 083 461 6096.

This MAN is issued in the interest of aviation and public safety.



Director of Civil Aviation

Date 2010 -10- 28

Recipients of this notice are requested to ensure that these are copied to their in-house or contracted organisations, to relevant outside contractors, and to all members of their staff who could have interest in this information or who need to take appropriate action in response to this notice.