

Occurrences Reported Between: 01/06/08 and 30/06/08

Occurrence Date	Reference Number	Occurrence Type	Location	Province	Aircraft	Type of operation	Summary
01/06/08	8506 (ZU-APF)	Accident	KZN	KZN	RV6	Private	A/C flow into power lines
14/06/08	8507 (ZU-BCA)	Accident	Salt Rock	KZN	Windlass Trike	Private	A/C spiraled & crashed into sea
24/06/08	8508 (ZU-EXT)	Accident	Rand Airport	GP	Extra 300	Private	Ruder cable failed, veered off runway on landing
26/06/08	8509 (ZS-FMP)	Accident	Maputo	O/B	Piper PA 28-235	Private	L/H main gear collided with heap of bags next to the runway
28/6/08	8510 (ZS-HWP)	Accident	Tzaneen (Ebenezar Dam)	Limp	Robinson R 44	Private	Pilot was flying over the dam. a/c fell into the dam
28/06/08	8511 (ZS-KIA)	Fatal Acc	Hammarisdale	KZN	Piper PA 28-236	Private	In-flight break-up (2 fatalities)



ZS-KIA in-flight break-up

Issued by Accident and Incidents Investigations Department

Enquiries:
Ms Bongzi Mngomezulu
Researcher - AIID
011 545 1238
083 451 2683
mngomezulub@caa.co.za

Remember to report hazards to cahrs@caa.co.za or via fax line at 011 545 1453