

Aircraft Occurrences in September 2009

Statistics reflect accident information entered into the computer by the research office and are current as of the date of this document. The data herein is dynamic and is therefore subject to change due to updated information.

Accident Ref	Date of Occ	Aircraft Type	Registration	Province	Area of Occurrence	Fatalities	Summary	Type of Operation
8689	01-Sep-09	Robinson R22	ZS-RMZ	NW	Fochville Area	0	Pilot lost directional control and collided with a tree	Part 127
8690	02-Sep-09	Mooney M20R	ZS-EOG	NC	Koffiefontein	0	Electrical problem in flight	Part 91
8691	06-Sep-09	Cherokee 180	ZS-AKS	GP	Grasmere	0	Engine failure followed by forced landing	Part 91
8692	24-Sep-09	Jetstream 41	ZS-NRM	KZN	Durban	1	Engine failure after take-off	Part 135
8694	25-Sep-09	Robinson R44I	ZS-RMN	GP	Annerdale	0	Over revving during flight - unsuccessful forced landing	Part 127
8693	26-Sep-09	Robinson R44II	ZS-RWD	GP	Muldersdrift	0	Power loss during take-off	Part 91

Issued by Accidents and Incidents Investigations Division

Research Section

Enquiries, please contact

Ms Bongekile Mngomezulu

011 545 1238

083 451 2683

aiidinbox@caa.co.za

Last date of update: 15 October 2009