

## Aircraft Occurrences in August 2010

*Statistics reflect accident information entered into the computer by the research office and are current as of the date of this document.*

*The data herein is dynamic and is therefore subject to change due to updated information.*

Accident Ref	Date of Occ	Aircraft Type	Registration	Province	Area of Occurrence	Fatalities	Summary	Type of Operation
8817	06-Aug-10	Robinson R 22	ZS-RVB	NC	Between Kenhardt and Poff-adder	2	Aircraft crashed fatally injuring the pilot and the passenger	Private
8818	09-Aug-10	Bantam B22J	ZU-EGU	MP	Near Hoedspruit Aerodrome	0	Gradual loss of power and height, followed by forced landing	Private
8819	13-Aug-10	Robinson R 44	ZS-CVW	MP	Near Ermelo	3	Wire strike	Private
8820	16-Aug-10	Grumman G164B	ZS-LEP	WC	Porteville Area	0	Pilot encountered a strong down draft, unable to control the aircraft and collided with the ground	Crop Spraying
8821	17-Aug-10	Piper PA 28-140 Cherokee	ZS-NFU	WC	Near Beauford West Aero	0	Wire Strike	Private
8822	21-Aug-10	Cheetah XLS	ZU-ETC	GP	Springs Aero	2	Aircraft impacted the ground in a nose down attitude	Private
8823	22-Aug-10	Piper PA 28-161 Warrior 2	ZS-PPB	KZN	Trevonton College Airfield	0	Pilot experienced a wind shear causing the aircraft to loose lift. a/c sank and impacted a wooden pole and ground	Private
8824	25-Aug-10	Auto Gyro	ZU-EEU	GP	Springs Aero	0	during landing roll, the gyrocopter's left hand side suddenly lifted in to the air. The gyro rolled over onto the right side and the main rotor blades impacted the ground	Private
8825	27-Aug-10	Auto Gyro GMBH	ZU-REA	GP	Brakpan Aero	0	Loss of directional control on landing, a/c veered to the right and damaged proper, rotor and rotor mast bent	Training
8826	28-Aug-10	Cubby	ZU-FAV	WC	Mosselbay Aero	0	in flight loss of engine power followed by forced landing	Private
8827	28-Aug-10	Piper PA-28	ZS-MII	GP	Brakpan Aero	0	Hard landing, a/c veered to the left of rnwy. A/c damaged nosewheel, propeller and engine	Private
8828	29-Aug-10	Lifelite/Dragonfly	ZU-TUG	KZN	Grass Route Aero	0	Hard landing, a/c veered to the right of the runway. a/c damaged left wing	Private

**Issued by Accidents and Incidents Investigations Division**

**Research Section**

**Enquiries, please contact**

**Ms Bongki Mtlokwa**

**011 545 1238**

**083 451 2683**

[aiidinbox@caa.co.za](mailto:aiidinbox@caa.co.za)

*Last date of update: 01 December 2010*