

## Aircraft Occurrences in November 2010

*Statistics reflect accident information entered into the computer by the research office and are current as of the date of this document.*

*The data herein is dynamic and is therefore subject to change due to updated information.*

Accident Ref	Date of Occ	Aircraft Type	Registration	Province	Area of Occurrence	Fatalities	Summary	Type of Operation
8860	01-Nov-10	Ela-07	ZU-DLL	Limp	Shelani Game Farm (Limp)	1	Pilot collided with high tension wires	Private
8861	02-Nov-10	Robinson R22	ZS-RNN	GP	Near Wonderboom	2	witnesses heard a loud bang and observed the aircraft twisting and crashed	Private
8862	07-Nov-10	Gyrocopter	ZU-DNH	EC	AJ Private Aero	0	aircraft loss power shortly after t/o, impacted the ground hard and damaged under carriage	Private
8863	07-Nov-10	Cessna 150	ZS-PPD	WC	George Aero	0	loss of control during landing due to electrical system failure	TBA
8864	13-Nov-10	Piper PA-31P-350 (MOJAVE)	ZS-JOA	GP	Kromdraai road near FALA	0	Engine failure due to fuel exhaustion	Test flight
8865	16-Nov-10	Beech - 58 Baron	ZS-KLP	KZN	Manzengwena Game Reserve	0	Pilot unable to stop the aircraft in time and exited the runway at the end. Propeller, nose landing gear, left wing leading edge damaged	Private
8866	08-Nov-10	PAJ3	ZS-AWJ	GP	Henley Aero Modelers Aerodrome	0	Wire strike	Private
8867	20-Nov-10	Solo Wing	ZU-BID	KZN	Escourt	0	Power loss in flight followed by wire strike	Private
8868	20-Nov-10	Ayres - Turbo Trush S-2R	ZS-JEL	MP	Secunda Aero	0	Power loss in flight and the aircraft impacted the ground	Private
8869	20-Nov-10	Piper PA-32	ZS-EYA	GP	Kitty Hawk	0	Pilot applied power but a/c did not respond. A/c landed short of runway and impacted the ground behind the airfield wire fence. a/c veered off to the right and sustained damaged on propeller, wings, nose landing gear broke	Private
8870	21-Nov-10	Rotary Air Force - RAF-2000	ZU-EPM	WC	Saldanha Aero	0	Gusty wind during t/o. pilot tried to land back, a/c rolled over, damages to the main rotor and tail rotor	Private
8871	22-Nov-10	Bantam B22J	ZU-DIA	GP	Hekpoort	0	Power loss during landing due to carburetor icing. Hard landing followed. A/c damaged	Private
8872	22-Nov-10	Robinson R22	ZS-RGE	NW	Private Farm in Mokopong	0	loss of power in-flight and a/c impacted a tree and rolled to its left hand side. Damages to main and tail rotor	Private
8873	27-Nov-10	Rainbow Aircraft	ZU-GFC	GP	Walkerville	0	a/c lost altitude and impacted a tree with the right wing before impacting the ground	Private
8874	30-Nov-10	Piper PA-46 Malibu	ZS-LLA	GP	Montana	0	Engine misfired and loss power	Test flight

**Issued by Accidents and Incidents Investigations Division**

**Research Section**

**Enquiries, please contact**

**Ms Bongzi Mtlokwa**

**011 545 1238**

**083 451 2683**

[aiidinbox@caa.co.za](mailto:aiidinbox@caa.co.za)

*Last date of update: 03 December 2010*