

Aircraft Occurrences in March 2011

Statistics reflect accident information entered into the computer by the research office and are current as of the date of this document. The data herein is dynamic and is therefore subject to change due to updated information.

Accident Ref	Date of Occ	Aircraft Type	Registration	Province	Area of Occurrence	Fatalities	Circumstances	Type of Operation
8904	05-Mar-11	Piper PA 28-180	ZS-SDR	MP	FAGL	0	Pilot lost control following a wind shear during landing	Private
8905	06-Mar-11	Schleicher K44 Rhonlerche II	ZS-GEA	KZN	Howick	1	the pilot did not gain sufficient altitude while gliding at a nearby ridge, was unable to glide back to airfield and impacted the ground	Private
8906	12-Mar-11	Cessna 182	ZS-FCP	GP	Bultfontein Airfield - Delmas	0	During landing, pilot encountered crosswinds which pushed the aircraft to the edge of the runway. Nose wheel dug in and broke off	Private
8907	13-Mar-11	Cessna 206	ZS-JCB	GP	Arrow Park - Delmas	0	Aircraft bounced during landing due unexpected gusting winds	Private
8908	09-Mar-11	Bantam	ZU-CZX	Limpopo	FAHT	0	Aircraft bounced during landing, landing gear collapsed	Private
8909	19-Mar-11	Cessna 150	ZS-JKN	MP	Machardodorp	1	Unsuccessful forced landing following a down draft resulting in a crash.	Private
8910	19-Feb-11	Aerotrike Cobra	ZU-CSS	Limpopo	Bela Bela	0	vibrations in before landing, a/c skidded on the runway and collided with a tree.	Private
8911	21-Mar-11	ELA-07-R115 Gyrocopter	ZU-RCY	MP	Driefontein-Witbank	0	unsuccessful forced landing following loss of power in flight	Private
8912	27-Mar-11	Cessna 206	ZS-PSC	WC	Delta 200 aerodrome	0	Unsuccessful forced landing following an in-flight engine failure	Private
8913	27-Mar-11	Bantam B22J	ZU-EFB	Limpopo	Private aerodrome near Tzaneen	0	Power loss and aircraft could not gain height and collided with trees.	Private
8914	08-Mar-11	Airtractor AT 401	ZS-NNY	Limpopo	Tzaneen	0	Unsuccessful forced landing due to engine failure	Agriculture
8915	29-Mar-11	Raven 500	ZU-SBC	GP	Brakpaan	0	Aircraft experienced a wind gust on landing and lost directional control	Private
8916	30-Mar-11	Zenon Gyrocopter	ZU-EXU	GP	FAKR	1	Gyrocopter rolled to the left during take-off	Private

Issued by Accidents and Incidents Investigations Division

Research Section

Enquiries, please contact

Ms Bongzi Mtlokwa

011 545 1238

083 451 2683

aiidinbox@caa.co.za

Last date of update: 04 May 2011