

Aircraft Occurrences in October 2011

Statistics reflect accident information entered into the computer by the research office and are current as of the date of this document. The data herein is dynamic and is therefore subject to change due to updated information.

Accident Ref	Date of Occ	Aircraft Type	Registration	Province	Area of Occurrence	Fatalities	Circumstances	Type of Operation
8961	4-Sep-2011	Jabiru SPT	ZU-CRV	MP	Witbank	0	Aircraft struck a tree with a right hand wing during low level flying.	Private
8972	8-Oct-2011	Bush Baby Explorer	ZU-FHY	KZN	Isithebe Aerodrome	0	In-flight engine failure followed by unsuccessful forced landing on uneven open field, Nose wheel collapsed, a/c overturned	Private
8973	12-Oct-2011	Embraer 120	ZS-PYO	Gabon	Port Gentil	0	Aircraft overshot a wet runway during landing	Scheduled
8974	15-Oct-2011	Airtractor AT401B	ZS-SRX	WC	Reversdale	0	Collision with power lines during crop spraying	Agriculture
8975	22-Oct-2011	YAK-52	ZU-DTL	KZN	Verginia (FAVG)	0	Aircraft lost control and collided with another stationary aircraft	Private
8976	22-Oct-2011	Cheetah XLS	ZU-EUJ	GP	Near Kitty Hawk	0	Aircraft overshot the runway during landing following a wind shear	Private
8977	21-Oct-2011	Pipper PA 28-140	ZS-EVJ	EC	Bisho (FABE)	0	during landing, student pilot stalled the a/c and crashed on the runway	Training

Enquiries, please contact

Ms Bongki Mtlokwa

011 545 1238

083 451 2683

aiidinbox@caa.co.za

Last date of update: 18 Nov 2011